Field Notes and Location Notices

7240



SE 1/4 Sec. 8

SW 1/4 SW 1/4 Sec. 8

SE 1/4 SW 1/4 Sec. 8
H.E. No. 900895

Sec. Cor. 7 | 8 / 18 | 17

W 1/16 Cor. 8/17

1/4 Cor. 8/17

N.64°38'30"E. 709.88

N.61°03'W. 635.22

N.80°17'W. 1784.12

N.84°13'W. 2973.66

N.89°56'E. 600.00

S.89°56'W. 600.00

S.0°04'E. 1500.00

N.0°04'W. 1500.00

S.0°04'E. 1149.45

N.0°04'W. 420.

N.0°04'W. 338.61

S.0°04'E. 1249.

N.0°04'W. 580

S.0°04'E. 1236.

N.0°04'W. 363.

438.74

316.12

300.00

1490.00

10.00

Disc. Point & Disc. Drill Hole

D.H. No. 182
D.H. No. 185
D.H. No. 184
D.H. No. 179
D.H. No. 151
D.H. No. 158
D.H. No. 156
D.H. No. 174
D.H. No. 157
D.H. No. 30
D.H. No. 139
D.H. No. 152
D.H. No. 67
D.H. No. 50
D.H. No. 89
D.H. No. 134
D.H. No. 45
D.H. No. 59
D.H. No. 67

YIKE No. 24
YIKE No. 26
YIKE No. 28
YIKE No. 17
YIKE No. 19
YIKE No. 21
YIKE No. 23
YIKE No. 25
YIKE No. 27
YIKE No. 29
YIKE No. 54
YIKE No. 56
YIKE No. 58
YIKE No. 60
YIKE No. 62
YIKE No. 64
YIKE No. 66
YIKE No. 68
YIKE No. 70

Sec. 18

Sec. 17

W.H.B.

True Meridian

800.

585.

534.

165.

360.

Note:
Reference will be made to the field notes for the numerous drill holes not shown hereon.

(See Sheet 3)

(See Sheet 2)

(See Sheet 3) (See Sheet 4)

687-1

7241

(See Sheet 4) (See Sheet 1)



(See Sheet 1)

(See Sheet 5)

YIKE No. 67

YIKE No. 68

YIKE No. 27

YIKE No. 28

YIKE No. 69

YIKE No. 70

YIKE No. 29

YIKE No. 71

YIKE No. 72

YIKE No. 31

YIKE No. 73

YIKE No. 74

YIKE No. 33

YIKE No. 75

YIKE No. 76

YIKE No. 35

Sec. 17

Sec. 8

STATE GRANT
Sec. 16

Note:
Reference will be made to the field notes for the numerous drill holes not shown hereon.

Sec. Cor. 8 | 9 / 17 | 16

1/4 Cor. 17|16

True Meridian

W.H.B.

687-2

7242

Sur. No. 687 Sheet 3 of 5




Note:
Reference will be made to the field notes for the numerous drill holes not shown hereon.

687-3

7243

( See Sheet 3 )

Sur. No. 687 Sheet 4 of 5




( See Sheet 1 )

( See Sheet 5 )( See Sheet 2 )

687—4

7244






Note:
Reference will be made to the field notes for the numerous drill holes not shown hereon.

W.H.B.

# MINERAL SURVEY No. 687 WYOMING

CLAIM OF

KERR—McGEE CORPORATION

KNOWN AS THE

YIKE Nos. 17, 19, 21, 23 to 29, 31, 33, 35, 51 to 76 AND 79 to 84 LODES

SITUATE IN

Secs. 8 & 16–20, T. 35 N., R. 74 W., 6th P.M.
CONVERSE COUNTY
Lat. 43° 00.6' N., Long. 105° 46.3' W.,
at Cor. No. 4, Yike No. 17 Lode

0 50 100 200 300 400 500 600
Feet
Magnetic Declination, 13°15' East

Surveyed, January 22 to March 27, 1973
By William G. Ladd, Mineral Surveyor

*UNITED STATES DEPARTMENT OF THE INTERIOR*
*BUREAU OF LAND MANAGEMENT*

*Cheyenne, Wyoming* *January 16, 1974*

*I hereby certify that this plat of Mineral Survey No. 687, Wyoming, is strictly conformable to the field notes of said survey which have been examined and approved.*

Richard A. Oakes

*Chief, Branch of Cadastral Surveys*

687-5