

Legend

- HJ Monitor Well
- Drawdown Contour (feet)
- Lost Creek Fault

Scale: 1:2,000

Lost Creek ISR, LLC
Littleton, Colorado, USA

Petrotek
www.petrotek.com
Littleton, CO USA

FIGURE 3.5-15
Drawdown in the HJ Aquifer at the End of the LC19M Pumping Test (2007)
Lost Creek Permit Area

Issued For: NRC ER
Drawn By: JM
Issued/ Revised: 10.22.07
Drawing No.: LC-ER Figure 3.5-15.mxd

0 150 300 Feet