

TOWNSHIP 12 NORTH, RANGE 60 WEST, OF THE SIXTH PRINCIPAL MERIDIAN, WYOMING.

CORRECTIVE DEPENDENT RESURVEY

SURVEY INFORMATION AND CERTIFICATE

This plat represents the entire record of the corrective dependent resurvey of the subdivision of section 4, Township 12 North, Range 60 West, Sixth Principal Meridian, Wyoming.

Sonja S. Sparks dependently resurveyed a portion of the Third Standard Parallel North, through Range 60 West, a portion of the subdivisional lines and the subdivision of section 4, in 2008.

During a meeting with landowners of this section, it was discovered by Ms. Sparks that the center 1/4 section corner of section 4 was not correctly positioned, which caused a difference in the distances on the North-South center line of this section. Additionally, it was discovered that in the process of recomputing the NAD 83 positions of the project control, only a portion of the corner locations translated to their corrected positions. The coordinates of those corrected positions, along with the corrective dependent resurvey correcting the 2008 dependent resurvey, are shown hereon.

Lottings and areas are as shown on the plat approved November 17, 1874.

The survey was executed with Trimble Model 5800 Global Positioning System (GPS) receivers. The GPS procedures used were in accordance with IM No. 2001-186, "Standard Guidelines for Cadastral Surveys Using Global Positioning System Methods" dated July 26, 2001. The directions of all lines are referenced to the true meridian. The directions, distances, and geographic positions were determined by GPS observations. The geographic positions of the following BLM control points based on NAD 83 (CORS 96) (EPOCH 2002) are:

NAME	LATITUDE	LONGITUDE	HAE
CP 1001	41°02'32.642"	104°03'54.151"	5307.79
CP 1002	41°01'50.256"	104°07'13.485"	5135.20

I, Sonja S. Sparks, Cadastral Surveyor, HEREBY CERTIFY upon honor that, in pursuance of Special Instructions dated April 9, 2009, and Assignment Instructions dated April 9, 2009, for Group Number 806, Wyoming, I have corrected a portion of the subdivision of section 4, Township 12 North, Range 60 West, Sixth Principal Meridian, Wyoming, and that this plat in one sheet represents the entire record of this survey. Survey commenced April 13, 2009, and completed April 15, 2009, and has been made in strict conformity with the special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, 1973, and in the specific manner described hereon.

Sonja S. Sparks
 Sonja S. Sparks
 Cadastral Surveyor

June 29, 2009
 Date

UNITED STATES DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT

Cheyenne, Wyoming June 29, 2009

This plat representing the entire record of this survey, having been correctly executed in accordance with the requirements of law and the regulations of this Bureau, is hereby accepted.

For the Director

John P. Lee
 John P. Lee
 Chief Cadastral Surveyor for Wyoming

Point for the center 1/4 sec. cor. of sec. 4, at intersection with the E. and W. center line.

From this point, the stainless steel post erroneously established during the 2008 dependent resurvey and subdivision as the center 1/4 sec. cor. of sec. 4, bears N.0°04'E., 1.11 chs. dist.

No evidence was found to indicate the erroneously established monument had been utilized by the public, therefore the decision was made to move the monument to its corrected position rather than amending it and setting a new monument.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, surrounded with three steel fence posts to protect the position, with brass cap mkd.

T12N R60W
 C 1/4 S 4
 2009

Cor. is located in wheat field, 3.09 chs. E. of fence line extending NNW. and SSE.

