

Table 4.2-1 Bulk Chemicals Required at the Permit Area

Shipped as Dry Bulk Solids	Shipped as Liquids and Gases
Sodium carbonate	Gasoline
Salt	Diesel fuel
Soda ash	Propane
Drilling mud	Oxygen
	Carbon dioxide
	Sulfuric acid
	Hydrogen peroxide
	Drilling mud