Click Here for Field Notes

5235



PLAT OF

HOMESTEAD ENTRY SURVEY No. 76

in the

SUNDANCE NATIONAL FOREST

in

Section 28, surveyed, T. 49 N., R. 60 W.,

of the

Sixth Principal Meridian,

Wyoming.

This plat of Homestead Entry Survey No. 76, situated in Section 28, surveyed, in Township 49 North of Range 60 West, and in Section ——— surveyed, in Township ——— of Range ——— and in Section ——— surveyed, in Township ——— of Range ——— and in Section ——— surveyed, in Township ——— of Range ——— of the ——— Sixth Principal Meridian is strictly conformable to the field notes of the Survey thereof, on file in this office, which have been examined and approved

Office of U.S. Surveyor General,
Cheyenne Wyoming.
August 9, 1915

Charles L. Decker
U.S. Surveyor General,
for Wyoming.

Scale
10 Chains equal 1 inch

Initials RDP

Surveys Designated	By Whom Surveyed	Instructions or Contract No	Instructions or Contract Date	When Surveyed Begun	When Surveyed Completed	Date of Approval
H.E. Survey No. 76	J. P. Davis, Surveyor Forest Service		Apr. 11, 1914	June 8	9, 1914	
" " " " 37	Albert B. Gidley					April 14, 1909
Subdivisions	Louis F. Stahle		Sept. 28, 1881	June 23	27, 1882	June 6, 1883
Resurvey State Line	Edward F. Stahle		July 1, 1904	June 12,	1905	Nov. 1, 1905

Areas			
H. E. Survey No. 76		Conflicts	
In Section 28	38.87		
In Section			
In Section			
In Section			
Total	38.87		

List No. 2-1801, Date May 24, 1913.
Act of June 11, 1906. Act of March 4, 1913.

Latitude 44° 11' 30" N.
Longitude 104° 03' 57" W. } At Cor. No. 1.
Mean Mag. Decl. 15° 24' E.

FORM 85-A

RMT

ENT. NO. 09558 NOTES
PAT. NO. 761867 Sept. 20, 1920 V
C. S. NO. P

76

Accepted by Commr Mch 1, 1916
Trans. to L.O. Mch 9, 1916