

Disturbance north of the Main Project Road is included in the Main Permit

Main Project Road

T25N- R92W-18

T25N- R92W-17


T25N- R92W-19

T25N- R92W-20


19

Staging Area

Office Trailer



Lost Creek ISR, LLC
Littleton, Colorado USA



AATA INTERNATIONAL, INC.
Fort Collins, Colorado, USA

Legend

- Perimeter Monitor Well
- MU1 Pipeline
- MU1 Powerline
- Secondary Roads
- - - Two Track
- - - Lost Creek Fault
- MU1 Existing Two Tracks
- - - Main Access Road
- MU1_Fenceline
- Culverts
- Top Soil Stock Piles
- MU1 Header House
- ▨ Staging Area and Shop
- MU1 Existing Structures
- MU1 Proposed Pattern Area
- ▭ Lost Creek Permit Area
- Lowland Big Sagebrush
- Upland Big Sagebrush

Figure MU1 3-2
MINE UNIT 1 VEGETATION DISTURBANCE
Lost Creek Permit Area

Issued For: WDEQ LQD 4.0 Drawn By: DS

Issued/Revised: 18 December 2009

Drawing No: WDEQLQD-D8.1

Contour Interval = 10 ft 0 400 Feet 1 in = 400 feet